

EMERGENCY LIGHTING PERIODIC INSPECTION REPORT

REPORT No: EMPIR-20250604200812

This is to certify that the emergency lighting installation at the address below
complies with the requirements of BS 5266-1:2016

South Petherton Youth Club
South Petherton
Somerset
TA13 5AU

And was deemed to be:

UNSATISFACTORY

Company issuing this Report

GO Electrical
Laurel Cottage, Brister End
Yetminster
Dorset
DT9 6NH
07828046579
garyoliverelectrical@gmail.com
CPS Enrolment No: 29965

Issued on

04/06/2025

Inspected by

Gary Oliver

Reviewed by

Gary Oliver

Recommended re-test



**1 Year from date
of issue**

Report generated by electraform® certification software 2025 | www.electraform.co.uk

REPORT NO: EMPIR-20250604200812

EMERGENCY LIGHTING INSPECTION AND TEST REPORT

For systems designed to BS 5266-1 and BSEN 50172 / BS 5266-8

DETAILS OF THE CLIENT		DETAILS OF THE INSTALLATION	
Reach Alternative Education - - -	☎: - 📠: - ✉: - 👤: Reach Alternative Education	- South Petherton Youth Club South Petherton Somerset TA13 5AU	☎: - 📠: - ✉: - 👤: -
DETAILS OF THE EMERGENCY LIGHTING INSTALLATION AND SYSTEM			
System manufacturer - Tel No - System installer - Tel No -		Luminaire types <input checked="" type="checkbox"/> Non-Maintained <input type="checkbox"/> Non-maintained luminaires, maintained signs <input checked="" type="checkbox"/> Maintained Other types - Responsible person -	System duration 3 hours <input type="checkbox"/> Automatic test fitted Date commissioned 27/05/2025
DETAILS OF ADDITIONS OR MODIFICATIONS TO THE SYSTEM SINCE ORIGINAL INSTALLATION			
Modification Number	Modification date	Modification location	Modification details
DETAILS OF THE COMPANY ISSUING THE COMPLIANCE CERTIFICATE			
Trading title GO Electrical		Postcode DT9 6NH	Company email garyoliverelectrical@gmail.com
Address Laurel Cottage, Brister End		Telephone no 07828046579	Website -
Town Yetminster		Mobile number -	
County Dorset		Enrolment no 29965	
DECLARATION			
Overall assessment of the installation in terms of its suitability for continued use:		UNSATISFACTORY	
Inspected and tested by Name Gary Oliver Position Electrician		Certificate authorised by Name Gary Oliver Position Electrician	
Signature  Date 27/05/2025		Signature  Date 04/06/2025	
NEXT INSPECTION			
I, recommend that this installation is further inspected and tested in			1 Year

Report produced by electraform® based on the MODEL FORM from BS5266:2016

EMERGENCY LIGHTING INSPECTION AND TEST RECORD

Test date	Test type	Which test	Test result	Engineer	No of faults reported
27/05/2025	Annual	2nd	Fail	Gary Oliver	2

FOR THE INSPECTION AND TESTING OF THE EMERGENCY LIGHTS

Name (Capitals)	Signature	Date
<div>Gary Oliver</div>	<div></div>	<div>27/05/2025</div>

Report produced by electroform[®] based on the MODEL FORM from BS5266:2016

EMERGENCY LIGHTING FAULT RECORD

Item No	Date of failure	Luminaire reference (if any)	Fault location	Action taken to safeguard premises	Action taken to rectify fault	Date of repair	Engineer
1	27/05/2025	02	Above main entrance internal	Booked to replace fitting, failed after 1.5 hors	Replace fitting	10/06/2025	Gary Oliver
2	27/05/2025	11	Above side door external	Booked to replace fitting, failed after 2 hours	Replace fitting	10/06/2025	Gary Oliver

FOR THE RECORDING OF FAULTS AND REPAIRS

Name (Capitals)	Signature	Date
<div>Gary Oliver</div>	<div></div>	<div>27/05/2025</div>

Report produced by electroform[®] based on the MODEL FORM from BS5266:2016